

NIAGARA STRAIGHT SIDE PRESSES

A-13-F-1

'C' TYPE CUSHION

1. Bolt
2. Pressure Plate
3. Cylinder Head
4. Roll Pin
5. Nut
6. Stud
7. Capscrew
8. Packing
9. Square Head Set Screw
10. Nut
11. Cylinder
12. Lubrication Piping
13. Spacer
14. Cylinder Mounting Plate
15. Bolt

